How to make a homing on the counter


On the main page, click on the touch with tools

15.11.2011 11:48:25

Click on the touch with a key

D
9300

15.11.2011 11:48:53

Here type
CEH460 in
capital letter

D

1000 h = 333333   0   0

3000 h = 1000000   0   0

Press on the touch and now the counter will
make an initialization.

After that you can start to run the machine.

SQ1Q   SQ1K

SQ1L